

February 13, 1984

Certified No. PO4 9037040

Mr. Jack Webster III, President
Webster Companies
2400 East Bennett
Springfield, Missouri 65804

Re: Harold Peck's 66
1211 W. Sunshine

Dear Mr. Webster:

On Tuesday, September 27, 1983, personnel from the City of Springfield's Water Pollution Control Section, Surveillance and Enforcement Branch, received a report of flammable hydrocarbon products entering the City's sanitary sewer system in the 1600-1800 block of South Fort. The hydrocarbon products were traced to Harold Peck's 66 service station at 1211 W. Sunshine. The tanks and fuel lines are owned by Webster Companies. You had the fuel lines and tanks tested as the City requested by Stoddard Equipment Company. As you know, leaks were found in the west regular storage tank, the no lead product line and the diesel vent line.

The ordinances of the City of Springfield provide for the recovery of the costs involved in the abatement of a violation under emergency conditions. By means of a copy of this letter, these costs are being certified to the Director of Finance as true and accurate costs incurred by the City of Springfield.

Attached to this letter is a detailed explanation of the costs incurred by the Water Pollution Control Section in the detection, monitoring, and treatment of flammable hydrocarbon products that have entered the City of Springfield's sanitary sewer system to November 29, 1983. Payment of these costs should be made to the City of Springfield, and sent to:

City of Springfield
City Hall, Room 210
830 Boonville
Springfield, MO 65802
Attention: Mr. Robert Schaefer

1600-1800 S. Fort.

Mr. Jack Webster III, President
February 13, 1984
Page 2

Due to the nature of the problem further action may be required to protect the health, life and property of those affected by the migration of lost hydrocarbon product.

Enclosed, please find a copy of Chapter 30 of the Springfield City Code. If you have any questions, please don't hesitate to call.

Yours truly,

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KC:js

Enclosure

cc: Robert R. Schaefer, P.E., Superintendent of Sanitary Services
Greg Perkins, Missouri Department of Natural Resources
Dale Bittle, Chief Fire Marshall
File

WATER AND SEWER COSTS:

September 27, 1983 to November 29, 1983

Water - 4560 ccf	1,922.55
Sewer - 4560 ccf @ .46/ccf	2,097.60
" - (Basic customer charge)	6.04

PERSONNEL COSTS: Surveillance & Enforcement

September 27, 1983 to November 29, 1983

	Burden Rate	Overtime Rate	Time at Site	Costs
Chandler	14.39		31.75	456.88
"		21.58	44.00	949.52
Corson	17.23		13.25	228.29
Pabst	17.23		5.25	90.46
Slaughter	14.39		.50	7.20
Short	14.39		.50	7.20

EQUIPMENT COSTS

Flusher (1 a crew of 3)	4.5 hrs. @ 59.28/hr.	311.76
P2-15		
P2-22	462 miles @ .35/mi.	<u>161.70</u>
P2-24		

TOTAL COST:**\$6,239.20**